Approved For Release 2002/08/28: CIA-RDP80B01676R002200020016-1

OGC 62-0516

OGC Has Reviewed

\$400 x 388.0

15 March 1962

MEMOR ANDUM	FOR:	Chief,	
-------------	------	--------	--

25X1

SUBJECT:

Francis Gary Powers - U-2

- 1. With regard to your question as to what caused the damage at altitude to Powers' plane, the following is condensed from talks with Dr. Scoville and technical representatives of the Department of Defense.
- 2. Assuming that the U-2 horizontal stabilizer failed at altitude, as we now believe, the shock wave required to cause this could be produced by a high explosive warhead of the size attributed to the SA-2 missile exploding in the neighborhood of 100-150 feet from the plane. At very high altitudes components of the fuel and high explosive composition could be expected to create an orange glow. This should be considered in the nature of a conjecture more than a conclusion. The possibility of a nuclear equipped warhead is much less likely, and there is no evidence to support such a possibility other than the fact that a nuclear warhead could more readily have created the shock wave.

el lancino a mana

LAWRENCE R. HOUSTON General Counsel

OGC:LRH:jeb O&l-Addressee l-Powers Board of Inquiry Files

Approved For Release 2002/08/28: CIA-RDP80B01676R002200020016-1

The second secon